

# Thor CV31

## UPS Battery Replacement Instructions

1021AB01

Anweisungen für Wechsel des UPS-Akkus

Instrucciones para reemplazar la batería de fuente de alimentación ininterrumpida (UPS)

Instructions relatives au remplacement de la batterie UPS

Istruzioni per la sostituzione della batteria del gruppo di continuità

UPS 電池交換手順

UPS 배터리 교체 지침





Instruções para Substituição da Bateria da UPS







Инструкции по замене батарейки ИБП






UPS Pili Değiştirme Talimatları

UPS 電池更換說明

UPS 電池更換指示







Patents. Patente. Patentes. Brevets. Brevetti. 특허. 특허 . Patentes. Патенты. Patentler. 专利。專利。  
[www.hsmpats.com](http://www.hsmpats.com)

Warranty. Garantie. Garantía. Garantie. Garanzia. 保証。보증 . Garantia. гарантия. Garanti. 保。保。  
[www.honeywellaidc.com/warranty\\_information](http://www.honeywellaidc.com/warranty_information)

## Honeywell Scanning & Mobility

9680 Old Bailes Road  
Fort Mill, SC 29707  
[www.honeywellaidc.com](http://www.honeywellaidc.com)



Thor CV31 UPS Battery (1021AB01) Replacement Instructions



P/N 943-410-001