

# **VEVOR**

**Affordable. Reliable. Home Improvement.**

## **ELECTRIC STARTER MOTORS**

**MODEL: 102-001L/QX-**

# VEVOR

Affordable. Reliable. Home Improvement.

ELECTRIC STARTER  
MOTORS

MODEL: 102-001L/QX-



This is the original instruction, please read all manual instructions carefully before operating. VEVOR reserves a clear interpretation of our user manual. The appearance of the product shall be subject to the product you received. Please forgive us that we won't inform you again if there are any technology or software updates on our product.



Warning-To reduce the risk of injury, user must read instructions manual carefully.

## **SAFETY WARNING INSTRUCTIONS FOR INSTALLATION**

- 1.Before installation, disassembly, or maintenance, firmly disconnect the battery power to avoid electric shock or short circuits.**
- 2.Prohibit operation in flammable and explosive environments to prevent sparks from causing hazards.**
- 3.Non-professionals shall not modify or repair without authorization to avoid component damage or safety accidents.**
- 4.Ensure the starter motor is firmly fixed during use to prevent loosening or detachment during operation.**
- 5.After replacing this electric starter motor, some vehicle models may experience idle instability. Clean the throttle valve promptly to ensure stable engine operation. If self-operation is difficult, consult a professional maintenance agency to avoid malfunctions from improper handling.**


## **INSTALLATION METHOD**

- 1.Positioning: Align the starter motor with the engine's installation position to ensure hole alignment.**
- 2.Fixing: Use mounting bolts to fasten the starter motor on the engine, ensuring no shaking.**
- 3.Wiring: Connect the battery's positive and negative power cords. Ensure correct positive/negative alignment to avoid reverse connection.**
- 4.Debugging: Power on, test the starting function briefly, and check for normal operation.**

## PRODUCT PARAMETERS

Model	Voltage	Power	OE
102-001L/QX-	DC12V	1600 (tolerance: +5, -10%)	PN6449

## ACCESSORIES LIST

Item	Qty	Picture
Electric Starter Motors	1	
<b>Vehicle Models Compatible With</b>		
<p>Compatible/Replacement for OLDSMOBILE                      Bravada V6 4.3L (1996-1998)                      Compatible/Replacement for ISUZU                      Hombre V6 4.3L (1997-1998)                      Compatible/Replacement for GMC                      Yukon XL 2500 V8 8.1L (2001-2002)                      Yukon V8 5.7L (1994-1999)                      W4500 Forward V8 5.7L (1998-2001)                      W3500 Forward V8 5.7L (1995-2001)                      T7500 V8 6.0L (1997-1998)                      T6500 V8 6.0L (1997-1998)                      Sonoma V6 4.3L (1996-1998)                      Sierra 3500 V8 8.1L (2001-2002)                      Sierra 2500 HD V8 8.1L (2001-2002)                      Savana 3500 V8 8.1L (2001-2002)                      Savana 3500 V8 7.4L (1996-2000)                      Savana 3500 V8 5.7L (1996-2002)                      Savana 2500 V8 5.7L (1996-2002)</p>		

Savana 2500 V8 5.0L (1999-2002)  
Savana 1500 V8 5.7L (1996-2002)  
Savana 1500 V8 5.0L (1999-2002)  
Safari V6 4.3L (1997-1998)  
P3500 V8 7.4L (1994-1999)  
P3500 V8 5.7L (1994-1999)  
P3500 V6 4.3L (1996-1999)  
K3500 V8 7.4L (1994-2000)  
K3500 V8 5.7L (1994-2000)  
K2500 Suburban V8 7.4L (1994-1999)  
K2500 Suburban V8 5.7L (1994-1999)  
K2500 V8 7.4L (1994-2000)  
K2500 V8 5.7L (1994-2000)  
K1500 Suburban V8 5.7L (1994-1999)  
K1500 V8 5.7L (1994-1999)  
K1500 V8 5.0L (1999)  
Jimmy V6 4.3L (1996-1998)  
G3500 V8 7.4L (1994-1996)  
G3500 V8 5.7L (1994-1996)  
G2500 V8 5.7L (1994-1995)  
C7500 Topkick V8 8.1L (2001-2006)  
C7500 Topkick V8 7.4L (1999-2000)  
C7500 Topkick V8 7.0L (1997-1998)  
C7500 Topkick V8 6.0L (1997-1998)  
C7500 Topkick V8 7.0L (1996)  
C6500 Topkick V8 8.1L (2001-2006)  
C6500 Topkick V8 7.4L (1999-2000)  
C6500 Topkick V8 7.0L (1997-1998)  
C6500 Topkick V8 6.0L (1997-1998)  
C5500 Topkick V8 8.1L (2003-2006)  
C3500HD V8 8.1L (2001-2002)  
C3500HD V8 7.4L (1994-2000)  
C3500HD V8 5.7L (1994-2000)

C3500 V8 7.4L (1994-2000)  
C3500 V8 5.7L (1994-2000)  
C2500 Suburban V8 7.4L (1994-1999)  
C2500 Suburban V8 5.7L (1994-1999)

Alternative OEM Numbers

106449L、1-06449L、12564108、12570823、18495、19136219、  
3231471、323-1471、330001419、3361910、336-1910、41012153、  
410-12153、41012153R、410-12153R、41012407、410-12407、  
41052422、410-52422、6449、9000879、SDR0019、SDR0019L、  
SDR0019-L、SND0776、10465578

## PRODUCT USAGE INSTRUCTIONS

- 1.Positioning:** Align the starter motor with the engine's installation position to ensure hole alignment.
- 2.Fixing:** Use mounting bolts to fasten the starter motor on the engine, ensuring no shaking.
- 3.Wiring:** Connect the battery's positive and negative power cords. Ensure correct positive/negative alignment to avoid reverse connection.
- 4.Debugging:** Power on, test the starting function briefly, and check for normal operation.
- 5.Confirm the engine is in normal condition before startup, with no abnormal jams.**
- 6.Connect battery power, briefly press the start button (or turn the key to the start gear). Single-start time should not exceed 5 seconds.**
- 7.If the engine fails to start initially, retry after a 10–15-second interval. Avoid continuous long-time starting to prevent motor damage.**

## CARE INSTRUCTIONS

- 1.Regular Inspection:** Monthly check for loose mounting bolts and oxidized or loose power cord connectors.
- 2.Cleaning Maintenance:** Every six months, clean dust and oil stains on the starter motor's surface to prevent impurities from affecting operation.
- 3.Lubrication Maintenance:** Add lubricating grease to transmission components (e.g., gears) every 1–2 years based on usage frequency to ensure smooth operation.
- 4.Fault Repair:** In case of issues like weak starting or abnormal noise, power off immediately and contact a professional for repair.

**Manufacturer:** Shanghaimuxinmuyeyouxiangongsi

**Address:** Shuangchenglu 803nong11hao1602A-1609shi, baoshanqu, shanghai 200000 CN.

**Imported to AUS:** SIHAO PTY LTD. 1 ROKEVA STREETEASTWOOD NSW 2122 Australia

**Imported to USA:** Sanven Technology Ltd. Suite 250, 9166 Anaheim Place, Rancho Cucamonga, CA 91730

<b>UK</b>	<b>REP</b>
-----------	------------

YH CONSULTING LIMITED. C/O YH Consulting Limited Office 147, Centurion House, London Road, Staines-upon-Thames, Surrey, TW18 4AX

<b>EC</b>	<b>REP</b>
-----------	------------

E-CrossStu GmbH  
Mainzer Landstr.69,  
60329 Frankfurt am Main.

