


DANCOVER[®]









Manual
for
Greenhouse Strong NOVA
2,1x3m




GREENHOUSE STRONG NOVA 2,1x3m





The company reserves the right to change the design in order to improve the consumer qualities of the product. Due to continuous improvement of product design and technological process there may be some minor differences between the datasheet and the product that do not reduce the consumer qualities of the product.











2x



1x

POLYCARBONATE REQUIREMENTS




2.1x3m

2x


1x

2.1x6m
+
1.05x6m



4 mm

NECESSARY TOOLS



1

P35

P32

P32

P6

P31

P31

2


2x

4216




PH2

2x



10706.0

3006+2006



2

4

1

2x

10506.0

3006

2006

3

2x

4216

2

2x






4216

2.1M

2x



P11



3

1

47x

40206

! 4

3x

P4

P1

2

4x


4216

3

2x

4216

!



← 2.32m → ← 2.32m →

2.1m





6m

2x

4

1




!


P33

P34



P34



2




3








P33

2x




5



6



7



Contact information

Austria



Belgium



Croatia



Denmark



Estonia



Finland



France



Germany



Ireland



Italy



Latvia



Lithuania



Nederland



Norway



Poland



Portugal



Spain



Sweden



Switzerland



UK

